CITY OF BALTIMORE WET W SMOKE AND DYED W Sewershed: Low Level	Page 1 of 3		
Subsewershed: 44	Company: REI/DRAYCO	Date: 08/25/2008	
Test Type: Smoke	Ground Condition: Dry: X Damp:_ Wet:_	Supervisor: E.R. Crew: 03	
Manhole ID: S17K049MH	Test ID: 1029-551	Notifications Made:X Residents, Fire, 311	
	d locations, defect locations and photograph nu	004	
2528	LH. JOHN	BLOWER #1 S17K_004MH	
MCHENRY	551_OBC	01-01 8" (265') 8" (265')	
2535 2539 2539 2539	2507 2509 2511 2511 2517 2517 2521 2521	300 302 304 306	

027

3/8

FREDERICK AV 1032

025

CITY OF BALTIMORE WET WEATHER CONSENT DECREE SMOKE AND DYED WATER TESTING FORM						Page 2 of 3			
,	Sewershed: Low Level Subsewershed: 44	Company: REI/DRAYCO				Date: 08/25/2008			
	Test Type: Smoke		Ground Condition:			Supervisor: E.R. Crew: 03			
· · · · · · · · · · · · · · · · · · ·		Dry: X Damp:_ Wet:_			<u> </u>	Notifications Made:X_ Residents, Fire, 311			
	nhole ID: S17K049MH		Test ID: 1029-551						
Field Sketch: (Show all manholes with numbers, blower placement location, sandbag or isolation locations, street names, building addresses and locations, defect locations and photograph numbers)									
Defect No.	Address	Source Type	Location	Sector	Drainage Area	Severity	Photo Number		
1	MCHENRY ST. & S CATHERINE ST.	12	01	01	13000	03	1029-551_OB01-01.jpg		
						1			
						-			
						1			
		OB	SERVAT	ION CO	DES				
	Source Type		Location			Sector	Severity		
	ain Sewer 10 MH Frame	01 Paved C				Public	01 No Smoke		
	ervice Line 11 Storm Drain eanout 12 Catch Basin	02 Asphalt		Field/W	oods 02	Private	02 Trace 03 Moderate		
	ownspout 13 Storm MH	03 Paved C 04 Drivewa		Golf Co	urse		03 Moderate 04 Major		
	ea Drain 14 Storm Ditch	05 Sidewal	,	Other	4130		o i iviajoi		
	vy. Drain 15 Excavation	06 Curb	- ` `						
	air. Drain 16 Water Line	07 Yard - F	ront						
	ound. Drai 17 Tele. Pole	08 Yard - B							
09 Blo	dg. Interio 18 Other	09 Yard - S	ide						

PAGE 3 OF 3

CITY OF BALTIMORE SMOKE TESTING OBSERVATION SUMMARY LOW LEVEL SEWERSHED

BALTIMORE CITY PROJECT 1029 REI/DRAYCO

Unique Test ID: 551 Date: 08/25/2008 Basin: LL - 44 Manhole ID: S17K__049MH Defect No: OB01 Supervisor: E.R. Crew: 03 Dye Test Recommended: N

Location: MCHENRY ST. AND S. CATHERINE ST.

Source Type: 12 Catch Basin Sector: 01 Public

Location: 06 Curb Severity: 03 Moderate Drainage Area: 13000
Comments: SMOKE COMING FROM STORM DRAIN ON CORNER OF MCHENRY WITH S CATHERINE ST.

SMOKE TEST PHOTOGRAPHS



Photograph No: OB01-01 Filename: 1029-551_OB01-01.jpg